SGS

SGS TAIWAN Ltd.

LABORATORY TESTING CENTER

136-1 Wu Kung Road,
Wuku Ind. Zone, Taipei County
Taipei, Taiwan.
Tel:(02)22993939,22993279~81
Fax:(02)22993227,22993237,22997857

266, CHUNG HWA 2ND ROAD
San Min District
Kaohsiung, Taiwan.
Tel: (07)3230920
Fax:(07)3215489

Test Report

U-CHIN FURNITURE CO., LTD.
NO.31-7, SEC.2, CHUNG SHAN ROAD,
TAI PAO CITY, CHIA YI,
TAIWAN, R.O.C.

Report NO : HL50113 /98/SL
Page : 1 OF 1
Date : JUN · 05, 1998

The following merchandise was submitted and identified by the client as:

Type of Product: PP ARMRESTS
Style/Item No.: AR305
Country of Origin: TAIWAN

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Required:
For compliance with ANSI/BIFMA X5.1-1993 (General Purpose Office Chairs) on clause number:
(14) Arm strength test-Vertical-Static.
(15) Arm strength test-Horizonal-Static.

Test Method:
Teasted according to test procedures of the ANSI/BIFMA X5.1-1993 standard.

Test Results:
ANSI/BIFMA X5.1-1993 (General Purpose Office Chair) Clause No:

14. Arm Strength Test-Vertical — Pass
Tested to subsection 14.3 test procedures
--Apply 200 lbs. functional load on arm for 1 minute and maintain until deflection is stabilized.
--Apply 300 lbs. proof load and repeat above procedure.
Requirement: No structural failure or loss of serviceability.

15. Arm Strength Test-Horizonal — Pass
Tested to subsection 15.3 test procedures
--Apply 100 lbs. functional load at the most forward point of armrest for 1 minute and maintain until deflection is stabilized.
--Apply 150 lbs. proof load and repeat above procedure.
Requirement: No structural failure or loss of serviceability.

Conclusion:
In our opinion, the submitted sample complies with clause number (14) and (15) of ANSI/BIFMA X5.1-1993 standard for General Purpose Office Chairs.

* This test document cannot be reproduced in any way, except in full context, without the prior approval in writing of the laboratory.

Prepared and checked by

329314

Signed for and on behalf of
SGS TAIWAN Ltd.

The report is not valid without an official stamp

LA35-98.3.5000