

**Test Report No.:** 0154063709a 001

Page 1 of 3

**Client:** Songlin Furniture Co., Ltd.

B Block, Jinli Industrial Zone, Sanxing Road, Saliang Village, Sanjiao Town,  
Zhongshan City, Guangdong Prov., China 528400

**Sample Description As Declared :**

No. Of Sample : One (1)  
Material : Textile  
Colour : Black  
Style No. : VPC#: SL-D2, SKU#: 6840306  
Product Description : Designer Chair Black Realspace Mid Back Tahari UK Fire Retardant

**Applicant's Provided  
Care Instruction/Label :** -

**Sample Receiving date:** 2014-09-03

**Delivery condition:** Apparent good, Samples tested as received

**Test Period:** 2014-09-03 to 2014-09-11

**For and on behalf of  
TÜV Rheinland (Shanghai) Co., Ltd.**



2014-09-11

Tina Wu / Department Manager

Date

Name/Position

*Test result is drawn according to the kind and extent of tests performed.*

*This test report relates to the a. m. test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products.*

Test Report No.: 0154063709a 001

Page 2 of 3

**Conclusion**M001

Abrasion resistance

P

Note : P = Pass

# = No Comment

N/A = Not Applicable

F = Fail

- = Did Not Perform

\* = See Remark

**Material list**

Material No.	Material	Color	Location
M001	Textile	Black	Seat, backrest

Test Report No.: 0154063709a 001

Page 3 of 3

**1. Abrasion Resistance**

Test method : ISO 12947-2:1998

No. of Breakdown	<u>M001</u> >30000 Rubs	<u>Requirement</u> 30000
------------------	-------------------------------	-----------------------------

Sample Photo:



- END -